13886 Clarkesville Pike, Clarkesville Howard County, Maryland

The house at 13886 Clarkesville Pike has a two-story, two-bay by one-bay frame structure at its core, with a gable roof that has an east-west ridge and asphalt shingle roofing. This house has aluminum siding over top of German siding, with the front of the house facing south. There is a one-story addition on the south that has brick veneer and a gable roof with a north-south ridge. There is a one-story shed-roofed addition on the east side of the main block. The main block has a two-story ell that is two bays by one bay, with a gable roof that has a north-south ridge and aluminum siding. There is a one-story, long, shed-roofed addition on the east side of this ell, with the roof sloping down to the north, and this building is set to the north of the other shed-roofed addition on the east, and extends well to the east. This building has some German siding. On the north side of this addition is a one-story brick veneered, hip-roofed addition. It is also on the east side of the ell. There is a one-story hipped-roof addition on the west side of the ell, with a porch that continues over the west side of the main block to connect this addition to the previously mentioned south addition. This west addition has brick veneer, and brick veneer was added to the west side of the main block on the first story at the same time. The original house has a lobby entry plan that has an enclosed straight run of stairs in the center. The room to the right has a modern kitchen with the east end wall removed for the eastern addition to enlarge this room. The room to the left, or west, has had the south wall opened up for the south addition, circa in the 1950s. The house has drywall and all new windows, doors, and trim. The rear ell configuration has been completely altered.

The house at 13886 Clarksville Pike began as a three-bay, two-story frame structure with a lobby entry and an enclosed straight stairway in the center dividing the two front rooms in the main block. There was a kitchen ell that was apparently one story. Based on the form of the building and the construction visible, it was probably built in the late nineteenth or very early twentieth centuries. The house has undergone considerable alterations, beginning with an addition on the east to enlarge that room. Apparently in the 1950s an addition was made on the front and the front wall of the west room opened up. Additions were made on almost every part of the first story, and on the second story of the ell, and almost all of the historic fabric on the interior was removed and replaced, leaving little left of the original historic house.

Maryland Historical Trust Maryland Inventory of Historic Properties Form

Inventory No.

HO-926

| 1. Name of P | roperty | (indicate preferred | name) | | | | | |
|---|--|---|-------------|---------------|------|----------|------------------------|---------|
| historic | | | | | | | | - F |
| other | | | | | | | | |
| 2. Location | | | | | | | | |
| street and number | 13886 Clarksv | rille Pike | | | | no | ot for publ | ication |
| city, town | Clarksville | | | | | X v | icinity | |
| county | Howard | | | | | | | |
| 3. Owner of F | roperty | (give names and mailing | g addresses | of all owners | s) | | | |
| name | 13886 Clarksv | rille Pike LLC | | ji. | | | | |
| street and number | 13886 Clarksv | rille Pike | 8 | :B | te | elephone | 301-8 | 54-3004 |
| city, town | Clarksville | | state | MD | Z | ip code | 20777 | |
| Contributing R Contributing R Determined El Determined In Recorded by H | Resource in Nationa Resource in Local H igible for the Natio eligible for the Nat | nal Register/Maryland Re ional Register/Maryland F | egister | | | | * | - |
| 6. Classificat | ion | | | 0 | | | | |
| | Ownership | Current Function | | | Resc | ource Co | unt Noncontr | A |

7. Description

Inventory No.

HO-926

Condition

Prepare both a one paragraph summary and a comprehensive description of the resource and its various elements as it exists today.

The house at 13886 Clarkesville Pike has a two-story, two-bay by one-bay frame structure at its core, with a gable roof that has an east-west ridge and asphalt shingle roofing. This house has aluminum siding over top of German siding, with the front of the house facing south. There is a one-story addition on the south that has brick veneer and a gable roof with a north-south ridge. There is a one-story shed-roofed addition on the east side of the main block. The main block has a two-story ell that is two bays by one bay, with a gable roof that has a north-south ridge and aluminum siding. There is a one-story, long, shed-roofed addition on the east side of this ell, with the roof sloping down to the north, and this building is set to the north of the other shed-roofed addition on the east, and extends well to the east. This building has some German siding. On the north side of this addition is a one-story brick veneered, hip-roofed addition. It is also on the east side of the ell. There is a one-story hipped-roof addition on the west side of the ell, with a porch that continues over the west side of the main block to connect this addition to the previously mentioned south addition. This west addition has brick veneer, and brick veneer was added to the west side of the main block on the first story at the same time.

The basement was a crawl space that has been excavated, with CMUs added below the rubble stone foundation walls. The rubble stone walls have been opened up for the numerous additions that encase this house. None of the framing is visible in the floor above.

The original house has a lobby entry plan that has an enclosed straight run of stairs in the center. The room to the right has a modern kitchen with the east end wall removed for the eastern addition to enlarge this room. The room to the left, or west, has had the south wall opened up for the south addition, circa in the 1950s. This room also has a cupboard and shelves built in on the north wall at about the same time. The house has drywall, all new windows, doors, and trim, and has 2 1/2-inch pine flooring that runs east-west. The rear ell configuration has been completely altered.

The second-story plan follows that of the first story. The room on the east has been completely reconfigured. There is no access to the attic. According to the owner, the previous owner added the room over the ell c. 1991. The northeast corner of the house is exposed on the second story, and the wall has a 3-inch by 4-inch sash-sawn corner post and 2 by 4 sash-sawn studs with cut nails.

| 8. Signifi | cance | Inventory No. HO-926 |
|--|---|--|
| Period 1600-16991700-17991800-18991900-19992000- | Areas of Significance agriculture archeology X architecture art commerce communications | Check and justify below — economics — health/medicine — performing arts — education — industry — philospohy — engineering — invention — politics/government — entertainment/ — landscape architecture — religion recreation — law — science — ethnic heritage — literature — social history |
| Specific date | community planning conservation | |
| Construction | n dates c. 1899 | |
| Evaluation fo | r: | |
| National Register | | Maryland Register X not evaluated |

Prepare a one-paragraph summary statement of significance addressing applicable criteria, followed by a narrative discussion of the history of the resource and its context. (For compliance reports, complete evaluation on a DOE Form - see manual.)

The house at 13886 Clarksville Pike began as a three-bay, two-story frame structure with a lobby entry and an enclosed straight stairway in the center dividing the two front rooms in the main block. There was a kitchen ell that was apparently one story. Based on the form of the building and the construction visible, it was probably built in the late nineteenth or very early twentieth centuries. The house has undergone considerable alterations, beginning with an addition on the east to enlarge that room. Apparently in the 1950s an addition was made on the front and the front wall of the west room opened up. Additions were made on almost every part of the first story, and on the second story of the ell, and almost all of the historic fabric on the interior was removed and replaced, leaving little left of the original historic house.

9. Major Bibliographical References

Inventory No. HO-926

See continuation sheet. Footnotes.

10. Geographical Data

Acreage of surveyed property 2 A

Acreage of historical setting

Quadrangle name

Clarksville

Quadrangle scale __1:24000

Verbal boundary description and justification

The boundary on the south follows the drive to the west of the house, then runs north to the base of the hill behind the house, runs along this hill to east of the garage, and then turns south to the drive.

11. Form Prepared By

| name/title | Ken Short | | | |
|---|--|------------------------|----------------|--|
| organization | Howard County Dept. of Planning & Zoning | date | 7/23/2007 | |
| street and number 3430 Courthouse Drive | | telephone 410-313-4335 | | |
| city or town | Ellicott City | state MD | zip code 21043 | |

The Maryland Inventory of Historic Properties was officially created by an Act of the Maryland Legislature to be found in the Annotated Code of Maryland, Article 41, Section 181 KA, 1974 supplement.

The survey and inventory are being prepared for information and record purposes only and do not constitute any infringement of individual property rights.

return to:


Maryland Historical Trust

DHCD/DHCP

100 Community Place

Crownsville MD 21032

410-514-7600





HO-926 Ken Short, June 2007 1/4

13886 Clarksville Pike South elevation



HO-926 Ken Short, June 2007 2/4

13886 Clarksville Pike East elevation



HO-926 Ken Short, June 2007 3/4

13886 Clarksville Pike East & north elevations



HO-926 Ken Short, June 2007 4/4

13886 Clarksville Pike West elevation

HO-0926 20070622 01

13886 Clarksville Pike Howard County, Maryland South elevation Ken Short June 2007 1/4

HO-0926_20070622_02

13886 Clarksville Pike Howard County, Maryland East elevation Ken Short June 2007 2/4

HO-0926_20070622_03

13886 Clarksville Pike Howard County, Maryland East & north elevations Ken Short June 2007 3/4

HO-0926 20070622 04

13886 Clarksville Pike Howard County, Maryland West elevation Ken Short June 2007 4/4